




**RETROFITTING & CONVERSION > RETROFIT SMARTPHONE INTEGRATION PACKAGE -  
AZ82.60-P-0028NKA****MODEL 117.3/9 up to 11/30/15, 156.9156.9 up to 11/30/15, 176.0 up to 11/30/15, 242.8 up to 11/30/15, 246.2 up to 11/30/15 with CODE 531 (COMAND APS) except CODE 14U (Smartphone integration package)**

## MODIFICATION NOTES

03.03.2016	Work procedure modified	Commissioning removed.	
	<b>Remove/install</b>		
1	Exchange multimedia connection unit in front stowage compartment		
		Model 117, 156, 176, 242, 246 as of model year 2016	AR82.60-P-1032NKM
	<b>Update Vehicle Documentation (VeDoc)</b>		
2	Enter special equipment in online vehicle data card	 <b>Code 14U</b> (Smartphone integration package) <b>Code 16U</b> (Smartphone integration Carplay) <b>Code 17U</b> (Smartphone integration Google Automotive Link)	
3	Attach note "Smartphone integration package retrofitted as per AZ82.60-P-0028NKA " under field organization texts to DG 82		

4 Connect charger and  
charge battery




AR54.10-P-1130NKB

5 Connect diagnostic system  
and select vehicle using  
vehicle identification number  
(FIN)



AD00.00-P-2000-04A


6 Perform software update for head unit  Variant coding using  
software calibration number  
(SCN) is integrated in the  
software update.

7 Disconnect diagnostic  
system

8 Disconnect battery charger



### Check

9 Perform function test  See operator's manual  
for smartphone integration  
package.

### PARTS ORDERING NOTE

Part no.	Designation	Quantity
KG 98	Smartphone integration package parts kit	1